

CENTRO DE FRESADO K76

RELACIÓN DE HERRAMIENTAS EN EL ALMACÉN

CÓDIGO HTA.	DENOMINACIÓN	LONGITUD DE TRABAJO
T02D02	Fresa Ø 2	4 mm
T04D04	Fresa Ø 4	12 mm
T05D05	Broca Ø 5	25 mm
T06D06	Fresa Ø 6	12 mm
T07D07	Broca Ø 7	25 mm
T08D08	Fresa Ø 8	16 mm
T09D09	Broca Ø 9	30 mm
T10D10	Fresa Ø 10	30 mm
T11D11	Broca Ø 10	30 mm
T12D12	Fresa Ø 12	16 mm
T13D13	Mandrino 11,5	16 mm
T14D14	Fresa Ø 14	18 mm
T15D15	Broca Ø 14	30 mm
T16D16	Fresa Ø 16	20 mm
T18D18	Fresa Ø 18	20 mm
T20D20	Fresa Ø 20	25 mm
T21D21	Fresa de planear Ø 60	4 mm
T24D24	Posición siempre libre de herramienta	